



g) a thermometer:



$$\text{Precision} = \frac{10^\circ\text{C}}{2 \text{ ticks}} = \boxed{5^\circ\text{C}}$$

h) a fuel gauge:



$$\text{Precision} = \frac{1 \text{ tank}}{2 \text{ ticks}} \Rightarrow \frac{1}{2} \text{ tank}$$

$$\text{Precision} = \frac{1}{2} \text{ tank of gas}$$